


# SB/SBA







Further product  
documentation







[net.grundfos.com/qr/i/99057358](http://net.grundfos.com/qr/i/99057358)

be  
think  
innovate

**GRUNDFOS** 






**SB**  
**SBA**



STRAINER

SIDE INLET


3/4"



1"







SB HF



**SB**  
**SBA**

STRAINER




SIDE INLET



**SB**

**STRAINER**

**SIDE INLET**




**SBA**

**STRAINER**



**SBA**


**SIDE INLET**




SB  
SBA

STRAINER

SIDE INLET






SB HF








Max. 20 starts per 60 minutes.



SB HF



Max. 30 starts per 60 minutes.





be think innovate

---

**98159397** 0418

ECM: 1232283

**GRUNDFOS Holding A/S**

Poul Due Jensens Vej 7  
DK-8850 Bjerringbro  
Teli: +45 87 50 14 00  
[www.grundfos.com](http://www.grundfos.com)

**GRUNDFOS** 

The name Grundfos, the Grundfos logo, and be think innovate are registered trademarks owned by Grundfos Holding A/S or Grundfos A/S, Denmark. All rights reserved worldwide.